

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/06/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155669</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01</b>  B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>08/04/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>RIVERVIEW TCU</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>395 WESTFIELD RD TCU</b> <b>NOBLESVILLE, IN 46060</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	INITIAL COMMENTS  Paper compliance to the Life Safety Code Recertification and State Licensure Survey conducted on 07/20/15 was completed on 08/04/14.5  Review Date: 08/04/15  Facility Number: 011046 Provider Number: 155669 AIM Number: NA  Based on review of the Fire Safety Evaluation System (FSSES) Survey conducted on 07/27/2015, Riverview TCU was found in compliance with NFPA (National Fire Protection Association) 101A, Chapter 4, Fire Safety Evaluation System for Health Care Occupancies in regard to the PSR to the Life Safety Recertification and State Licensure Survey. Achieving a passing score on the FSSES Survey for Health Care Occupancies found in Chapter 4 of NFPA 101A, Alternative Approaches to Life Safety, 2001 Edition, shows the facility provides a level of Life Safety at least equivalent to that prescribed by NFPA 101, Life Safety Code (LSC and 410 IAC 16.2.	{K 000}			
{K 032} SS=F	NFPA 101 LIFE SAFETY CODE STANDARD  Not less than two exits, remote from each other, are provided for each floor or fire section of the building. Only one of these two exits may be a horizontal exit. 19.2.4.1, 19.2.4.2          This STANDARD is not met as evidenced by:	{K 032}			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/06/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155669</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01</b>  B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>08/04/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>RIVERVIEW TCU</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>395 WESTFIELD RD TCU</b> <b>NOBLESVILLE, IN 46060</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 032}	Continued From page 1 Based on observation and interview, the facility failed to ensure 2 of 2 smoke compartments were provided with at least one exit providing a continuous path of travel to an exit discharge. This deficient practice affects all residents, staff and visitors.  Findings include:  Based on observations with the Administrator during a tour of the facility from 11:10 a.m. to 12:20 p.m. on 07/20/15, the TCU has two emergency exits. One exit is a horizontal exit into the adjacent smoke compartment. The adjacent smoke compartment has two exit stairwells. The second exit is an exit stairwell which does not connect to an exit discharge directly to the exterior. Based on interview at the time of the observations, the Administrator acknowledged each smoke compartment is not provided with at least one exit discharging directly to the exterior of the building.	{K 032}	Correction Obviated - Passed FSES		
{K 034} SS=F	3.1-19(b) NFPA 101 LIFE SAFETY CODE STANDARD  Stairways and smokeproof towers used as exits are in accordance with 7.2. 19.2.2.3, 19.2.2.4  This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to provide a continuous protected path of travel to an exit discharge for 3 of 3 exits in accordance with LSC sections 7.2.3.5. LSC 7.2.3.5 requires every smokeproof enclosure	{K 034}	Correction Obviated - Passed FSES		

DEPARTMENT OF HEALTH AND HUMAN SERVICES  
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/06/2015  
FORM APPROVED  
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  <b>155669</b>	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>01</b>  B. WING _____		(X3) DATE SURVEY COMPLETED  <b>R</b> <b>08/04/2015</b>
NAME OF PROVIDER OR SUPPLIER  <b>RIVERVIEW TCU</b>			STREET ADDRESS, CITY, STATE, ZIP CODE <b>395 WESTFIELD RD TCU</b> <b>NOBLESVILLE, IN 46060</b>		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 034}	<p>Continued From page 2</p> <p>shall discharge into a public way, into a yard or court having direct access to a public way, or into an exit passageway. Such exit passageways shall be without openings other than the entrance from the smokeproof enclosure and the door to the outside yard, court, or public way. The exit passageway shall be separated from the remainder of the building by a two hour fire resistance rating. This deficient practice affects all residents, staff and visitors.</p> <p>Findings include:</p> <p>Based on observations with the Administrator during a tour of the facility from 11:10 a.m. to 12:20 p.m. on 07/20/15, the fourth floor on which the TCU is located is divided into two smoke compartments and has three stairwell exits. Additionally, the fire resistance rating of the three exit enclosures on the first floor of the hospital to the exit discharge door is less than two hours. Based on interview at the time of the observations, the Administrator acknowledged each of the three exit discharge passageways are not separated from the remainder of the building by a two hour fire resistance rating.</p> <p>3.1-19(b)</p>	{K 034}			